	Signer	Weight Change	SATES (126 140 146 146 146 146 146 146 146 146 146 146	Wisch, Dirio
U PILOT OTHERS	ΑI	RFRAME		LURE	ENGIN	E FAILURE	
UNIT No.31 S.F.T.S. COM. Kingston, Ont. # 1	PL	SES O .ACE	M • A	A C C I D E N T S	DATE 13-3-4		
A/C Harvard II TYPE Harvard II	N	AJ660		CRASH B C 2	SE X ME	DAY X NIGHT	0 0 46 75
NAME	RANK	No.	ץזעם	וחראו	RIES	SERIOUS	A E C
Bloomer,	LT.		PP	Nil		FATAL INJURY	
Barraclough,	ALA	FX95501	PP	Nil			m z m oth
N						SERIAL NO.	S C C C C C C C C C C C C C C C C C C C
TYPE A/F NO. EXTENT OF DAMAG	E REP		DAT	E	ON TYPE	TOTAL LAST	a rep
Harvard II AJ660 Serious	3			INST. NIGHT	DUAL SOLO DI	UAL SOLO 6 MOS.	
Wasp S3H1 9627 Ni1 Harvard II AJ690 Slight Wasp S3H1 101281 Ni1 SIGNAL NO. & DATE UNIT NO. & C 32 14-3-43	DATE	сом.	No &	DATE REPOR	· FILE	DATE	- 0 m 0 7 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4

(DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER)				
	Flying training - formation flying.	OR COMMANDING OFFICER'S REPORT:)				
		D-14.					
	NATURE OF ACCIDENT AND STAGE OF FLIGHT: Pilot of AJ690 failed to notice	DATE:	,				
	AJ660 standing outside Base, while	COMPOSITION:)				
	he was taxiing. On turning to port)				
	in order to reach runway stbd. wing of AJ690 came into contact with tal unit of plane AJ660, causing conside damage to AJ660 as AJ690 swung to starboard.	Irecommendations.))				
	PRIMARY CAUSE:						
1	24. Carelessness.						
1	9. Callisean)				
	9	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER)				
	(A) Pupil pilot's Log Book to be endorsed						
	"Carelessness", and pilot to be interviewed						
ŀ		by Station Commanding Officer.	, ·				
	secondary cause or contributing factors: 3. Hitting other aircraft.		,				
	Congestion of A/C at arming point.	RECORDED BY	DATE				
)						
)	CHECKED BY	DATE)				