

## CASPIR Aircraft Accident Cards

---

**Serial:** FE446

**Title:** North American Harvard Mk. IIB serial:FE446 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-March-24. Harvard II s/n FE446. This accident involved 2 people. Blackburn EW, Brown JT

**Keywords:** RAFHarvard II,FE446,41 SFTS,41 Service Flying Training School,Aerodrome,1943-March-24,Blackburn,BrownRCAF L20

**Created:** 1943-03-24

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE446>



DUTY ON WHICH ENGAGED:

Instructors' instrument flying.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While attempting to land A/C struck snow and overturned. Pilot mistook snow between runways for the only runway which was serviceable.

DATE:

COMPOSITION:

D-14 ✓  
S W ✓

RECOMMENDATIONS:

PRIMARY CAUSE:

32. Pilot error.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

37. Overturning.

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_