

CASPIR Aircraft Accident Cards

Serial: FP726

Title: Avro Anson Mk. II serial:FP726 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-March-05. Anson II s/n FP726. This accident involved 2 people. Sanders DE, Laubman DW

Keywords: RCAFAnson II,FP726,7 SFTS,7 Service Flying Training School,Aerodrome,1943-March-05,Laubman,SandersRCAF L20

Created: 1943-03-05

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP726>

DUTY ON WHICH ENGAGED:

Training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Brakes failed while A/C taxiing down wind in close proximity to the hangar line. A/C swung towards the hangars and collided with the main doors.

DATE:

COMPOSITION:

TCC/PCT/LBF^{D-14}

RECOMMENDATIONS:

The instructors are reminded of the fact that in case of brake failure immediate use of the throttles for steering purposes is necessary, and the A/C is to be swung clear of traffic, facing into wind with the engines shut off.

PRIMARY CAUSE:

~~**7. Brake failure.**~~

11. Others

11

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~**Inexperience on part of instructor.**~~

36. Brake failure 36

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____