

## CASPIR Aircraft Accident Cards

---

**Serial:** FP852

**Title:** Avro Anson Mk. II serial:FP852 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-March-11. Anson II s/n FP852. This accident involved 1 person. Stead ER

**Keywords:** RAFAnson II,FP852,38 SFTS,38 Service Flying Training School,Aerodrome,1943-March-11,SteadRCAF L20

**Created:** 1943-03-11

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP852>



DUTY ON WHICH ENGAGED:

Night circuits and landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C came in to land at night.  
Given red light by A.C.P. A/C  
response was slow, A/C rolled to  
stbd but A/C hit ground at wind-  
ward edge of runway.

DATE:

D-14

COMPOSITION:

L0/P50

RECOMMENDATIONS:

PRIMARY CAUSE:

~~29. Overshooting runway.~~

1. *overshot*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~18. Loss of control.~~

~~25. Inexperience.~~

RECORDED BY

DATE

CHECKED BY

DATE