

CASPIR Aircraft Accident Cards

Serial: 8209

Title: Avro Anson Mk. II serial:8209 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1943-March-26. They are: Anson II s/n FP705, Anson II s/n 8209. This accident involved 2 people. Chapin MF, Mays M

Keywords: RCAFAnson II,8209,9 SFTS,9 Service Flying Training School,Aerodrome,1943-March-26,Chapin,MaysRCAF L20

Created: 1943-03-26

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8209>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Instrument instruction.

OR COMMANDING OFFICER'S REPORT:

D-14.

MOLY

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

A/C 8209 piloted by F/S Chapin taxied into parked A/C FP705 while leaving tarmac. No pilot in FP705. No damage to A/C 8209. Rudder damaged on FP705.

COMPOSITION:

*TEA / PCT
MA / AA*

RECOMMENDATIONS:

PRIMARY CAUSE:

3. Hitting other aircraft.

9. collisions

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

(A) Pilot's Log Book endorsed.

Pilot placed on charge for negligence.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~24. Carelessness.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____