

CATEGORY TYPE OF ENGINE TYPE OF ACCIDENT
 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19
 20 21 22 23 24 25 26 27 28 29 30

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE					
CAUSES OF ACCIDENTS													
UNIT 3 W.S. Winnipeg			COM. 2		PLACE Stevenson Field Winnipeg, Man.			DATE 22-3-43		TIME 1550			
A/C TYPE Fleet Fort 11			No. 3637		CRASH CAT. C 10		SE X	ME	DAY X	NIGHT			
NAME				RANK	No.	DUTY	INJURIES			SERIOUS			
McArthur, W.J.				Sgt.	R134229	P.	Nil.			FATAL	INJURY		
Whitehead, H.D.				Lac.	R169676	WO	N;L.						
CARD SERIAL No.													
TYPE A/F & ENGINE		No.	EXTENT OF DAMAGE		REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS					
Fort 3637 Slightly			Jacobs L6MB 26786/10040 Slightly					INST.	NIGHT	ON TYPE		TOTAL	LAST 6 MOS.
										DUAL	SOLO	DUAL	SOLO
SIGNAL No. & DATE		UNIT No. & DATE			COM. No. & DATE		REPORT		FILE		DATE		
A-12		23-3-43											
NATURE OF ACCIDENT													

MISCELLANEOUS CAUSES
 HAND Q.
 INSTS.
 WEATHER
 DRKMS.
 ALG SURF.
 OTHER
 UND TO
 PRIMARY
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ.
 INJURY
 3RD.
 S.
 2.
 1.
 30
 29
 28
 27
 26
 25
 24
 23
 22
 21
 20
 19
 18
 17
 16
 15
 14
 13
 12
 11
 10
 9
 8
 7
 6
 5
 4
 3
 2
 1

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30
 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70
 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90
 91 92 93 94 95 96 97 98 99 100

DUTY ON WHICH ENGAGED:

Wireless exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Landed near edge of runway, stbd wheel struck soft snow and overturned.

DATE:

COMPOSITION:

LA / P5J

RECOMMENDATIONS:

PRIMARY CAUSE:

~~4. Bad surface.~~

7. Others

7

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

37. ~~Overturning.~~

RECORDED BY

DATE

CHECKED BY

DATE