

CATEGORY
 TYPE OF ENGINE
 TYPE OF A/C
 TYPE OF ACCIDENT

PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE					
CAUSES OF ACCIDENTS													
UNIT		COM.		PLACE				DATE		TIME			
20 E.F.T.S. Oshawa, Ont.		1		Tarmac - Oshawa				25-3-43		1210			
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY NIGHT			
Tiger Moth Tiger Moth		5122 9677		C 2½ D		x		x					
NAME			RANK	No.	DUTY		INJURIES			SERIOUS			
Corbett, V.J.E.			Lac.	R169249	PP		Nil.			FATAL INJURY			
Jackson, J.A.			Lac.	R170695	PP		Nil.						
Thompson, F.W.			Lac.	R184958	PP		Nil. (9677)						
									CARD SERIAL NO.				
									J				
TYPE A/F & ENGINE		No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS						
Tiger Moth 5122		Seriously	Nil.	Nil.	Nil.	Nil.	INST.	NIGHT	ON TYPE		TOTAL		LAST 6 MOS.
G. Major 12834/89017									DUAL	SOLO	DUAL	SOLO	
Tiger Moth 9677		Slightly	Nil.	Nil.	Nil.	Nil.							
G. Major 12877/89057													
SIGNAL No. & DATE		UNIT No. & DATE			COM. No. & DATE			REPORT		FILE		DATE	
A-47 25-3-43													

STAGE OF FLIGHT
 TAKE-OFF
 FLIGHT
 STRATRY
 FATAL
 INJURY
 INJ. BRO.
 R.F.

STAGE OF FLIGHT
 LANDING
 TAXIING
 PRIMARY
 UNINTD
 OTHER
 ALG SURF
 DRKNS.
 WEATHER
 INSTS.
 HANDO.

MISCELLANEOUS CAUSES

NATURE OF ACCIDENT

DUTY ON WHICH ENGAGED:

5122 was taxiing.
9677 was parked.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While taxiing, misjudged distance from parked A/C. Stbd mainplane came in contact with idling propellor of parked A/C.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

MULT D-14

DATE:

COMPOSITION:

TCA/105
TCA/118

RECOMMENDATIONS:

PRIMARY CAUSE:

~~3. Hitting other A/C.~~

9. Collision

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed and 7 days heavy extra duties.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~24. Carelessness.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____