

DUTY ON WHICH ENGAGED:

#5 Navigation Exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Engine failed and A/C force landed.
Port wing of A/C had struck a fence
post, ripping off the wing tip and
causing the A/C to cartwheel. The
tail hit a second post, ripping off
the lower half of the rudder.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~58. Precautionary landings.~~

No apparent cause for engine failure.

~~Deemed to be probable low flying.~~

17. Forced Landing

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~41. Hitting obstructions~~

26. Engine trouble Accident

RECORDED BY

DATE

CHECKED BY

DATE