

## CASPIR Aircraft Accident Cards

---

**Serial:** FE325

**Title:** North American Harvard Mk. IIB serial:FE325 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-April-05. Harvard II s/n FE325. This accident involved 1 person. Turton FM

**Keywords:** RAFHarvard II,FE325,41 SFTS,41 Service Flying Training School,R1 Halbrite,1943-April-05,TurtonRCAF L20

**Created:** 1943-04-05

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE325>



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Sequence 17.

OR COMMANDING OFFICER'S REPORT:

✓  
D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Pilot while carrying out first solo  
on type, made allowance for drift but  
soon after touch down A/C ground looped.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~38. Ground loop.~~

2. *Stalling* (2)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~25. Inexperience.~~

\_\_\_\_\_  
RECORDED BY

\_\_\_\_\_  
DATE

\_\_\_\_\_  
CHECKED BY

\_\_\_\_\_  
DATE