

CASPIR Aircraft Accident Cards

Serial: AJ928

Title: North American Harvard Mk. II / 2 serial:AJ928 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-April-08. Harvard II s/n AJ928. This accident involved 2 people. Blackwood GD, Moody R

Keywords: RAFHarvard II,AJ928,41 SFTS,41 Service Flying Training School,Aerodrome,1943-April-08,Blackwood,MoodyRCAF L20

Created: 1943-04-08

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ928>

DUTY ON WHICH ENGAGED:
Landings and circuits.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
Taxiing towards windward side of
take off strip, noticed another A/C
about to take off. Instructor and
pupil both applied brakes, tail of
A/C lifted, causing propellor to
touch runway.

DATE:
COMPOSITION:

1/11/51

D-14 ✓
10/11/51

RECOMMENDATIONS:

PRIMARY CAUSE:

~~4. Harsh use of brakes.~~

11. Letter

11

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~36. Nosing up.~~

RECORDED BY

DATE

CHECKED BY

DATE