

CASPIR Aircraft Accident Cards

Serial: FE318

Title: North American Harvard Mk. IIB serial:FE318 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-April-10. Harvard II s/n FE318. This accident involved 1 person. Longstaff GB

Keywords: RAFHarvard II,FE318,41 SFTS,41 Service Flying Training School,Aerodrome,1943-April-10,LongstaffRCAF L20

Created: 1943-04-10

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE318>

DUTY ON WHICH ENGAGED:

Aerobatics.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot making cross wind landing, failed to correct drift sufficiently. Pilot took overshoot action but failed to prevent A/C touching down in soft ground. A/C nosed up.

DATE:

D-14



COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~35. Cross winds and gusts.~~

7. Others

(7)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~36. Nosing up.~~

32. Pilot error.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____