



DUTY ON WHICH ENGAGED:

A/C being taxied along tarmac.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Harvard AJ794 collided with Harvard AJ762 while taxiing on tarmac.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~3. Hitting other aircraft.~~

9. Collision

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed "Gross Carelessness". Confined to camp for 14 days.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

24. Carelessness.

RECORDED BY

DATE

CHECKED BY

DATE