

CASPIR Aircraft Accident Cards

Serial: 2589

Title: North American Harvard Mk.II serial:2589 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-April-10. Harvard II s/n 2589. This accident involved 1 person. Singleton V

Keywords: RAFHarvard II,2589,41 SFTS,41 Service Flying Training School,Mont Martre,1943-April-10,SingletonRCAF L20

Created: 1943-04-10

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2589>

DUTY ON WHICH ENGAGED:

No. 2 cross country.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14 ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pilot while carrying out cross country COMPOSITION:

flight, on checking fuel was down to 8 gallons in reserve, carried out a precautionary landing with U/C retracted.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~58. Precautionary landings.~~

17. Forced Landing

17

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~34. Wheels up landing.~~

~~53. No gas.~~

25 Petrol Shortage 25

R.C.A.F. FORM L20 REQ. 1247 10M-15-17-41

RECORDED BY

DATE

CHECKED BY

DATE