

CASPIR Aircraft Accident Cards

Serial: AJ194

Title: Harvard II serial:AJ194 - Crash Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-April-14. Harvard II s/n AJ194. This accident involved 1 person. Singleton V

Keywords: RAFHarvard II,AJ194,41 SFTS,41 Service Flying Training School,R1 Halbrite,1943-April-14,SingletonRCAF L20

Created: 1943-04-14

DUTY ON WHICH ENGAGED:

Precautionary landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

While taxiing after landing A/C commenced to swing. Pilot's hand accidentally opened the throttle, tail left ground and propellor touched runway.

DATE:

COMPOSITION:

TM/INT/PCDM ✓

D-14

RECOMMENDATIONS:

PRIMARY CAUSE:

~~4. Harsh use of brakes.~~

11. Others

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~61. Swinging on landing.~~

~~36. Nosing up.~~

~~32. Pilot error.~~

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____