

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	32	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																	
CAUSES OF ACCIDENTS																															
UNIT		COM.		PLACE				DATE		TIME																					
Camp Borden		#1 TC		M.A.				19.4.43		0900																					
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT																			
Harvard		FE.759		D.1/4		X				X																					
NAME			RANK	No.	DUTY	INJURIES				SERIOUS																					
Herron, V.A.			LAC	R165440	PP	Nil				FATAL		INJURY																			
TYPE A/F & ENGINE		No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS																								
Harvard		#FE.759	Slight				INST.	NIGHT	ON TYPE		TOTAL		LAST 6 MOS.																		
Wasp 42-15040/20403		Nil.																													
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE																					
C.429		20.4.43																													
NATURE OF ACCIDENT																															

CAUSES  
 MISCELLANEOUS  
 FLIGHT STAGE OF

UNDTD  
 PRIMARY  
 UNDTD  
 HAND Q.  
 INSTS.  
 WEATHER  
 DRINKS  
 ALG SURF.  
 OTHER  
 UNDTD  
 PRIMARY  
 TAXIING  
 LANDING  
 TAKE-OFF  
 FLIGHT  
 STATRY  
 FATAL  
 INJ.  
 3RD  
 INJURY

9

1

DUTY ON WHICH ENGAGED:  
Sequences 6,7,8,15,13.

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:  
Damaged wing tip through ground loop. COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:  
38. Ground loop.

ACTION TAKEN:  
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER  
7 days C.B. Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:  
32. Pilot error.

\_\_\_\_\_  
RECORDED BY DATE

\_\_\_\_\_  
CHECKED BY DATE