

## CASPIR Aircraft Accident Cards

---

**Serial:** FE340

**Title:** North American Harvard Mk. IIB serial:FE340 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 2 aircraft on 1943-April-20. They are: Harvard II s/n AJ937, Harvard II s/n FE340. This accident involved 2 people. Hoyland P, Carvosso AFH

**Keywords:** RAFHarvard II,FE340,41 SFTS,41 Service Flying Training School,Aerodrome,1943-April-20,Carvosso,HoylandRCAF L20

**Created:** 1943-04-20

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE340>



DUTY ON WHICH ENGAGED:

Precautionary landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pilot following landing taxied off runway but taxied into A/C parked at edge of connecting strip due to tire trouble.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~3. Hitting other aircraft.~~

9. Collisions

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER  
7 days C.C. and grounded for 1 month.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~24. Carelessness~~

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_

✓ D-14