



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Night flying.

OR COMMANDING OFFICER'S REPORT:

D.14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Taxiing out on first detail of night flying taxied into parked a/c 2759 on taxi strip. Navigation lights were switched on in a/c 2759 prior to the accident.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~3. Hitting other aircraft.~~

9. collisions

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Action under T.C.I. 3/16

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~24. Carelessness.~~

62. Taxiing too fast.

RECORDED BY

DATE

CHECKED BY

DATE