

CASPIR Aircraft Accident Cards

Serial: 3841

Title: North American Harvard Mk. II serial:3841 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-April-24. Harvard II s/n 3841. This accident involved 2 people. Martin SW, Ferguson JG

Keywords: RAFHarvard II,3841,41 SFTS,41 Service Flying Training School,Aerodrome,1943-April-24,Ferguson,MartinRCAF L20

Created: 1943-04-24

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#3841>

DUTY ON WHICH ENGAGED:

Night Circuits and landings

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil N/F dual under complete darkness made 3 successful landings, but on the 4th bounced slightly, swung slowly towards flares and applied brake harshly causing A/C to turn over.

DATE:

D.14

COMPOSITION:

LM/ATO PSS/I/INT/UCP ✓

RECOMMENDATIONS:

PRIMARY CAUSE:

~~37. Overturning~~

2. *Swung*

(2)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~61. Swinging on landing~~

4. ~~Harsh use of brakes.~~

RECORDED BY

DATE

CHECKED BY

DATE