

## CASPIR Aircraft Accident Cards

---

**Serial:** FE281

**Title:** North American Harvard Mk. IIB serial:FE281 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-April-25. Harvard II s/n FE281. This accident involved 1 person. Burns DR

**Keywords:** RAFHarvard II,FE281,41 SFTS,41 Service Flying Training School,R1 Halbrite,1943-April-25,BurnsRCAF L20

**Created:** 1943-04-25

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE281>



DUTY ON WHICH ENGAGED:

Precautionary landing practice

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil pilot landed at R.1 with U/C retracted.

DATE:

D.14

COMPOSITION:



RECOMMENDATIONS:

PRIMARY CAUSE:

~~34. Wheels up landing~~

7. Others

7

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pupil severely reprimanded and ability under review.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~24. Carelessness~~

32. U/C Drill - In

32

air

RECORDED BY

DATE

CHECKED BY

DATE