

CASPIR Aircraft Accident Cards

Serial: FE339

Title: North American Harvard Mk. IIB serial:FE339 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-April-25. Harvard II s/n FE339. This accident involved 1 person. Jackson FJ

Keywords: RAFHarvard II,FE339,41 SFTS,41 Service Flying Training School,Aerodrome,1943-April-25,JacksonRCAF L20

Created: 1943-04-25

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE339>

DUTY ON WHICH ENGAGED:

Circuits and landings

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D14

LM/ANT/PSS/PCM/JRP ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Inexperienced pupil allowed A/C to swing on landing, failed to correct, applied brakes harshly and tipped A/C on nose and port mainplane.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~61. Swinging on landing~~

2. Seewing.

2

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log Book endorsed "Inexperience".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~36. Nosing up~~

~~4. Harsh application of brakes~~

RECORDED BY

DATE

CHECKED BY

DATE