

## CASPIR Aircraft Accident Cards

---

**Serial:** FE279

**Title:** North American Harvard Mk. IIB serial:FE279 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-April-26. Harvard II s/n FE279. This accident involved 1 person. Grant W

**Keywords:** RAFHarvard II,FE279,41 SFTS,41 Service Flying Training School,Aerodrome,1943-April-26,GrantRCAF L20

**Created:** 1943-04-26

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE279>



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Night flying.

OR COMMANDING OFFICER'S REPORT:

D-14.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pupil taxiing down no.1 taxi strip. COMPOSITION:

Another A/C taxied out of apron on to taxi strip and appeared to be so near that it would have been unavoidable to miss it without full application of RECOMMENDATIONS: brakes, on doing so A/C 279 tipped over on to its nose.

PRIMARY CAUSE:

~~4. Harsh use of brakes.~~

11. *Others*

11

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

(A) Log Book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~62. Taxiing too fast.~~

RECORDED BY

DATE

CHECKED BY

DATE