32 31 - 32 31 2 35		/////		20 19 18 20 19 18 25 18 17 5 6 18	17 17 18 18 18 18 18 18 18 18 18 18 18 18 18	16 15 14 13  AHUL OR HOURT	//,	ool chir ligh	7 3	6 5	
				FRAME		CHO ME	7		FAIL		
PE OF A/6	C A			USES OF ACCIDENTS PLACE 7 miles SW Cabri, Sask.				DATE 28.4.43 TIME1720 H.O. FILE 1300-FE.309			Notation of the state of the st
<b>-/▶</b> /	A/C TYPE Harvard I	I	No.	FE.30	9	CRASH CAT. B	SE X	ME I	X	NIGHT	15101/32/
	NAM	E	RANK	No.	DUTY	טנאו	RIES		SERIO	ous	A CRACIANT
											S CHE
<u> </u>	TYPE A/F NO	TYPE A/F No. EXTENT		RT SERIAL	DAT	E HO	URS FLOWN BY P				1 1 1 / 8 / /
4 2	Harvard I	OF DAMAG		ous i		INST. NIGHT	ON TY		SOLO	LAST 6 MOS.	[] - V & / /
16 4 4 A GORY	Wasp A.N.105	1/14465	Ser	ous :							A C E C E C E C E C E C E C E C E C E C
17 0 0 0 CATE	A.448 29.4.				No. & [	A C C I D E N T		FILE	D	ATE	
	2/3/1/5/6 6 7 5 9	4 8 6 01 1	\\$\\\ 2\\	URE	91 9	7 7 7 7	\v\v\v\	23 24 SZ	20 20 gr	/ n / n e	

J			<b>,</b> / , , , , , , ,
)	DUTY ON WHICH ENGAGED: CO	URT OF INQUIRY, INVESTIGATING OFFICER	
)	Distance Courses In-1-3-3-4 to the	COMMANDING OFFICER'S REPORT:	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT: DA	D-14.	
)	S/L Rogers flew to scene of forced collanding to bring the A/C back, and	MPOSITION: TO NT	
)	) from the air and ground the field ap-		
)	peared excellent as it was stubble.  On take off Harvard ran forward about 50 vds. When stbd. wheel sank in softs.	201115117151717	
)	50 yds. when stbd. wheel sank in soften sand. A/C tipped on nose and caught	COMMENDATIONS:	
)	fire. Fire was finally put out with soil, etc. Most of damage was from fi		
)	PRIMARY CAUSE:	re.	
```	1. Bad surface of aerodrome.		
)	10 Bad Shound.	•	
)		TION TAKEN:	
		(A) Disciplinary (B) Technical (C) Other	
,	)	MIL	)
)			
)	)		
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
)	36. Nosing up.	RECORDE	'D DV
)	30 Love - On Ground	KECORDE	D BY DATE
)	R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED	D BY DATE
1			