

CASPIR Aircraft Accident Cards

Serial: FP734

Title: Avro Anson Mk. II serial:FP734 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-April-06. Anson II s/n FP734. This accident involved 2 people. Keys MR, Olson BW

Keywords: RCAFAnson II,FP734,15 SFTS,15 Service Flying Training School,Aerodrome,1943-April-06,Keys,OlsonRCAF L20

Created: 1943-04-06

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP734>

DUTY ON WHICH ENGAGED:
Dual instruction.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

D-14 ←

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
Pupil landed fast and A/C swung to the left. Instructor tried to correct with brake and engine but brakes did not work. A/C left runway and soft mud increased swing. U/C collapsed.

DATE:
COMPOSITION:

LS/PS/PT / U/C F / USS

RECOMMENDATIONS:

PRIMARY CAUSE:

~~61. Swinging on landing.~~

2. *Swung.*

2

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~46. Brake failure.~~

~~44. Bad surface.~~

36. *Brake Failure*

36

RECORDED BY

DATE

CHECKED BY

DATE