

## CASPIR Aircraft Accident Cards

---

**Serial:** 8250

**Title:** Avro Anson Mk. II serial:8250 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1943-April-18. Anson II s/n 8250. This accident involved 1 person. Spratt RW

**Keywords:** RCAFAnson II,8250,5 SFTS,5 Service Flying Training School,Aerodrome,1943-April-18,SprattRCAF L20

**Created:** 1943-04-18

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8250>



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Seq. 25.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Port engine cut out on night circuit.  
A/C unable to maintain altitude on  
remaining motor and student pilot  
carried out crash landing.

COMPOSITION:

*12 FEB 1966 / 1000 / 2510 / 1000 / 11  
D-14 ✓*

RECOMMENDATIONS:

PRIMARY CAUSE:

~~51. Engine failure in the air.~~

*17. Torced Landing*

*7*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

*Nil.*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

*26. Engine trouble - Accident*  
*26*

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_