

CASPIR Aircraft Accident Cards

Serial: 3657

Title: Fleet Fort serial:3657 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-April-13. Fleet Fort II s/n 3657. This accident involved 2 people. Parks WR, Ramsay MY

Keywords: RCAF Fleet Fort II,3657,2 WSFS,2 Wireless School Flying Squadron,Aerodrome,1943-April-13,Parks,RamsayRCAF L20

Created: 1943-04-13

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3657>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

D-14

Wireless training exercise.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

11/1/62

A/C took fire while taxiing after normal landing - due to gas line breaking and fuel spraying on hot motor. Pilot took necessary action to combat fire by using extinguisher. Fire extinguished with help of crash tender crew.

COMPOSITION:

RECOMMENDATIONS:

Relocation of fuel lines and request from engineering section for flexible fuel lines for permanent installation. Removal of line at 60 hr. check.

PRIMARY CAUSE:

~~12. Fire after landing.~~

11. Others

11

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~33. Technical defect.~~

30 Fire on Ground 30

RECORDED BY

DATE

CHECKED BY

DATE