

DUTY ON WHICH ENGAGED:

Preparation of aircraft for Dawn patrol

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Whilst preparing A/C AM772 for Dawn Patrol, the pilot allowed it to move forward for about 30 yds. after the chocks had been removed, causing it to collide with Hudson FK534, which was parked nearby.

DATE:

MAR 1
TCN/PET
MA/XII

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

3. ~~Hitting other aircraft.~~

9. collisions

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed "Carelessness".

Charge of negligence, dealt with summarily.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

24. Carelessness.

RECORDED BY

DATE

CHECKED BY

DATE