

## CASPIR Aircraft Accident Cards

---

**Serial:** AS223

**Title:** Airspeed Oxford Mk. II serial:AS223 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-April-01. Oxford II s/n AS223. This accident involved 2 people. Slater RA, Melener FEG

**Keywords:** RAF Oxford II, AS223, 35 SFTS, 35 Service Flying Training School, Cathkin Saskatchewan, 1943-April-01, Melener, Slater RCAF L20

**Created:** 1943-04-01

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS223>



DUTY ON WHICH ENGAGED:  
Low flying cross country.

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:  
A/C collided with telephone cable  
whilst flying low to identify position.

DATE:  
COMPOSITION:

1200/10N/WVG

RECOMMENDATIONS:

PRIMARY CAUSE:

~~20. Faulty navigation.~~

22. collisions Obstructions

22

ACTION TAKEN:  
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~19. Bad weather.~~  
41. Hitting obstructions.

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_