

## CASPIR Aircraft Accident Cards

---

**Serial:** BG433

**Title:** Airspeed Oxford Mk. II serial:BG433 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 2 aircraft on 1943-April-26. They are: Oxford II s/n AT446, Oxford II s/n BG433. This accident involved 1 person. Stock RA

**Keywords:** RAFOxford II,BG433,35 SFTS,35 Service Flying Training School,Aerodrome,1943-April-26,StockRCAF L20

**Created:** 1943-04-26

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#BG433>



DUTY ON WHICH ENGAGED:

Flying Training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14. *10/21*

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pupil attempted to taxi into position COMPOSITION:

on the parking line too close to another A/C and application of the

brakes had no effect, A/C BG433 running into AT446 which was sta-

tionary. It was discovered that compressed air container on BG433

PRIMARY CAUSE: was exhausted.

RECOMMENDATIONS:

~~7. Brake failure.~~

*9. ballistics 9*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

(A) Log Book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~3. Hitting other aircraft.~~

~~17. Disobedience of standing orders.~~

~~32. Pilot error.~~

*36. Brake Failure 36*

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_