

## CASPIR Aircraft Accident Cards

---

**Serial:** AS698

**Title:** Airspeed Oxford Mk. I serial:AS698 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-April-27. Oxford II s/n AS698. This accident involved 1 person. Constable RG

**Keywords:** RAF Oxford II, AS698, 35 SFTS, 35 Service Flying Training School, Prince Albert Aerodrome, 1943-April-27, Constable RCAF L20

**Created:** 1943-04-27

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS698>

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1						
19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1						
19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1						
19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1						
19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1						
19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1

TYPE OF A/C	PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE							
TYPE OF ENGINE	CAUSES OF ACCIDENTS															
UNIT	#35 S.F.T.S. North Battleford #4 TC				COM.	PLACE				DATE	27.4.43		TIME	0800		
A/C TYPE	Oxford II				No.	AS.698				CRASH CAT.	C.5		SE	ME	DAY	NIGHT
NAME	RANK		No.		DUTY		INJURIES				SERIOUS					
Constable, R.G.		Cpl		932543		PP		Nil				FATAL INJURY				
												CARD SERIAL No.				
												X				
TYPE A/F & ENGINE	No.		EXTENT OF DAMAGE		REPORT FORM	SERIAL No.	DATE		HOURS FLOWN BY PILOTS				LAST 6 MOS.			
Oxford II #AS.698				Slight					INST.	NIGHT	ON TYPE		TOTAL			
									DUAL	SOLO	DUAL	SOLO				
Cheetah X P.A179531 & S.A179484				Slight												
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE						
A.414		27.4.43														
NATURE OF ACCIDENT																

MISCELLANEOUS CAUSES

STAGE OF FLIGHT

UNDTD  
 PRIMARY  
 HANDQ.  
 INSTS.  
 WEATHER  
 DRINKS  
 ALG SURF.  
 OTHER  
 UNDTD  
 PRIMARY  
 TAXING  
 LANDING  
 TAKE-OFF  
 FLIGHT  
 STATRY  
 FATAL  
 INJ.  
 3RD.  
 4.  
 5.  
 6.  
 7.  
 8.  
 9.  
 10.  
 11.  
 12.  
 13.  
 14.  
 15.  
 16.  
 17.  
 18.  
 19.

DUTY ON WHICH ENGAGED:

Navigation cross country.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

When stbd. engine started the U/C collapsed breaking both airscrews. Subsequently the U/C lever was found to be fully down.

DATE:

COMPOSITION:

*TUC/PO/...*

RECOMMENDATIONS:

PRIMARY CAUSE:

~~5. Undercarriage drill on take off.~~

*8. U/C Failure*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot's Log Book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~24. Carelessness.~~

*23. U/C Drill on Ground.*

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_