

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Dual instruction being given to pupils in both A/C.

SUBJECT COMMANDING OFFICER'S REPORT:

MVLI
D-14

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Student in A/C 4375 landed with drift. A/C swung to the right upon landing. Brake lever stuck due to dog on brake lever being worn. A/C then collided with A/C 3940 which was parked prior to take-off.

COMPOSITION:

LCA/P300/UBR ✓
TCA/2A

RECOMMENDATIONS:

PRIMARY CAUSE:

~~33. Technical defect.~~

6. Collision (6)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~9. Hitting other aircraft.~~

~~46. Brake failure.~~

36. Brake Failure (36)

RECORDED BY

DATE

CHECKED BY

DATE