

CASPIR Aircraft Accident Cards

Serial: AH190

Title: North American Harvard Mk. II serial:AH190 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-May-02. Harvard II s/n AH190. This accident involved 1 person. Scall TH

Keywords: RAFHarvard II,AH190,41 SFTS,41 Service Flying Training School,Aerodrome,1943-May-02,ScallRCAF L20

Created: 1943-05-02

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AH190>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Night flying circuits and landings.

OR COMMANDING OFFICER'S REPORT:

D-14 # 7.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pupil pilot carrying out night flying circuits and landings made normal landing, A/C swung to port, stbd. brake was applied and right wheel stopped causing A/C to swing violently to right, when port oleo leg collapsed.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~38. Ground loop.~~

Swung.

2

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~46. Brake failure.~~

~~1. Bad surface of aerodrome.~~

u/c STRAIN

34

RECORDED BY

DATE

CHECKED BY

DATE