

CASPIR Aircraft Accident Cards

Serial: FE323

Title: North American Harvard Mk. IIB serial:FE323 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-May-04. Harvard II s/n FE323. This accident involved 1 person. Roberts LW

Keywords: RAFHarvard II,FE323,41 SFTS,41 Service Flying Training School,Halbrite R1,1943-May-04,RobertsRCAF L20

Created: 1943-05-04

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE323>

DUTY ON WHICH ENGAGED:

Precautionary landings

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

D.14 #20

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Made a good approach, but just before touch down, gust of wind caused stbd. wing to drop & touch runway, damaging mainplane.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~35. Cross winds and gusts~~

OTHERS.

7

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log Book endorsed "Inexperience"

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~25. Inexperience~~

RECORDED BY

DATE

CHECKED BY

DATE