إ			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1						1340 40 5(1) 10	A FUE			FAIL O		Waser Ing of W
A/C	PILOI	CAUSES OF ACCIDENTS													
9	UNIT #37 S.F.T.S. COM.			PLACE						DATE 12.5.43 TIME 1630				1 1 1 / .6	
E L	Calgary #4 TO			R.1, Airdrie						H.O. FILE 1300-AJ. 847			3 (4°/2)		
Ē	A/C TYPE HE	arvard II		No	AJ.8	47	CRAS CAT.	С.	2	SE X	ME		X	NIGHT	M I S O E L
_[NAME		RANK	No.	PUTY		1	וטנא	RIES			SERIC	ous	O E L L A L
Ì	Kemp	p, R.S.W.		PO	49610	PP	N	il					FATAL	INJURY	S A BY
ENGNE													CAR SERIA		S O NAO
PEOF						-							V		
7	TYPE A/F	PE A/F NO. EXTENT OF DAMAGE		REP	ORT SERIAL	DATE		ноц			URS FLOWN BY PILOTS				111/6
	& ENGINE	AT DAR			RM No.			INST.	NIGHT	ON T			SOLO	LAST 6 MOS	S T A TAKE
4	Harvard	072/70/7:	slightl	у	_			8	5	5	sc LO	49	41	-	
<u>۲</u>	Wasp	213679/ 1 :	730 NT	4								7/	74		101 V.S.
00				_			i			j					I O S S
¥TE	SIGNAL NO. & DATE UNIT NO. & DA			DATE	ATE COM. N		lo. & DATE		REPORT		FILE		DATE		
ΰſ	A.55	13.5.43				1									111

DÚTÝ ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFIC))))
solo practice flight	OR COMMANDING OFFICER'S REPORT:	D.14 # 6 5	
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Pupil pilot carrying out circuits and landings at R.1 made satis-	DATE: COMPOSITION:	√	
factory landing, but was followed by a ground loop.	RECOMMENDATIONS:	·	
PRIMARY CAUSE: 25. Inexperience Swung.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHE Log Book endorsed.	ER	
secondary cause or contributing factors: 38 Ground loop		RECORDED BY	DATE
)		CHECKED BY	DATE