

## CASPIR Aircraft Accident Cards

---

**Serial:** AJ929

**Title:** North American Harvard Mk. II serial:AJ929 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-May-13. Harvard II s/n AJ929. This accident involved 2 people. Armstrong, Howard HR

**Keywords:** RAFHarvard II,AJ929,41 SFTS,41 Service Flying Training School,Aerodrome,1943-May-13,Armstrong,HowardRCAF L20

**Created:** 1943-05-13

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ929>



DUTY ON WHICH ENGAGED:

circuits & landings

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D.14 #64

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil on solo test applied brakes harshly at low speed causing a/c to nose up.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~4. Harsh use of brakes~~

OTHERS.

11

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~36. Nosing up~~

~~29. Overshooting runway.~~

RECORDED BY

DATE

CHECKED BY

DATE