

CASPIR Aircraft Accident Cards

Serial: FE462

Title: North American Harvard Mk. IIB serial:FE462 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-May-16. Harvard IIB s/n FE462. This accident involved 1 person. Rigby K

Keywords: RAFHarvard IIB,FE462,41 SFTS,41 Service Flying Training School,Aerodrome,1943-May-16,RigbyRCAF L20

Created: 1943-05-16

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE462>

DUTY ON WHICH ENGAGED:

Circuits and landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14 #83

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil ground looped on landing.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~38. Ground loop.~~

SWUNG.

2

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

Pupil has been tested by Visiting Flight and by the C.I. and flying training discontinued.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE