-	SOLOT NO.		ALRERAME FAILURE					ENGINE FAILURE					O CO		
۷I	UNIT #13 S.F.T.S. COM.				USES OF ACCIDENTS PLACE					DATE 20.5.43 TIME 0900					NASTS!
A/0	St.Hubert 3			No.	M.A.			C•3		H.Q. FILE 1100		0-32-47] [-]	140
	NAME RAN				<u> </u>			INJURIES				SERIOUS			OHKWS.
					gt 414808 FI Nil C R164508 PP Nil						F	ATAL	YRULVI		OHER OTHER
PE OF ENGIN												CAR		o u s	Und A
	TYPE A/F No. EXTENT OF DAMAGE			REPORT SERIAL FORM No.		DATI	ATE HOL			FLOWN I	BY PILC	LOTS			101
	darvard	3247	Slight]		1 140.		INS	T. NIGHT	DUAL	TYPE SOLO	DUAL	SOLO	LAST 6 MOS.		
		06/0590_1	Nil.			CI I I I I I I I I I I I I I I I I I I	18	4 26 5	77 29	251 13	1.51 66	305 46		_ n	
J S	SIGNAL NO & DATE UNIT NO & DAT A. 226 20.5.43			ATE	E COM, No. & DATE			REPO	REPORT FILE			DATE		"	518 (8) (1) (2)

Seq. 19-17-22.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: D-14 #101
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Pilot made successful landing after which A/C began to swerve. A/C ground looped.	DATE:
))	RECOMMENDATIONS:
PRIMARY CAUSE: 32. Pilot error.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Log book endersed "Carelessness". Severe personal
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	admonition and given extra duties.
38. Ground loop. 24. Carelessness	RECORDED BY DATE