

CASPIR Aircraft Accident Cards

Serial: 2878

Title: North American Harvard Mk.II serial:2878 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-May-21. Harvard II s/n 2878. This accident involved 1 person. Scharning LA

Keywords: RAFHarvard II,2878,34 SFTS,34 Service Flying Training School,Aerodrome,1943-May-21,ScharningRCAF L20

Created: 1943-05-21

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2878>

DUTY ON WHICH ENGAGED:

Night flying circuits and landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14 #114

LM/GNT/PSS/PCM/URPV

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil landed and ran off the runway, harsh use of brakes causing A/C to tip on its nose.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~1. Swinging on landing.~~

2. SWUNG.

2

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~4. Harsh use of brakes.~~

~~36. Nosing up.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____