

CASPIR Aircraft Accident Cards

Serial: FE337

Title: North American Harvard Mk. IIB serial:FE337 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1943-May-21. They are: Harvard II s/n 3841, Harvard II s/n FE337. This accident involved 2 people. Tomlinson D, Curtis SR

Keywords: RAFHarvard II,FE337,41 SFTS,41 Service Flying Training School,Aerodrome,1943-May-21,Curtis,TomlinsonRCAF L20

Created: 1943-05-21

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE337>

DUTY ON WHICH ENGAGED:

FE337 - Air to ground firing.
3841 - Precautionary landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14 #109

DATE:

COMPOSITION:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Two Harvard A/C were approaching
to land on the same runway. FE337
completing its landing run, was
struck by 3841, which was still
airborne.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~15. Collision.~~

6

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

6. COLLISIONS

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____