٥		AIRFRAME	FAILUF				LURE	
OF A	UNIT 34 S.F.T.S. COM.	CAUSES O	F AC	CIDENTS	DATE 28	-5-43 TIME	1305	VE NETS (NETS)
ТҮРЕ	Hedicine Hat 4 A/C TYPE Harvard 11B	No. FESO7	M.A. CRA			1300-FES	NIGHT	S WERT
4	NAME	RANK No.	DUTY	ענאו			ERIOUS	C A C DRY
INE		Lac. 788096	PP	NiL.				0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
E OF ENGINE							CARD RIAL No.	SKITE /
ТУР	TYPE A/F NO EXTENT	REPORT SERIAL	DATE	но	URS FLOW	N BY PILOTS		1 1 / 87
	& ENGINE NO. OF DAMAG		DATE	INST. NIGHT	ON TYPE		LASI	1 1 / 4º/
RY -	Harvard 11B FE807 Sligh Wasp 21048/42-1124 NiL.	.010			37 20		4	
CATEGORY	SIGNAL NO. & DATE UNIT NO. &	DATE COM.	No. & DATE	REPOI	RT	FILE	DATE	

DUTY ON WHICH ENGAGED: Local solo exercises.	COURT OF INQUIRY, INVESTIGATING OFFICER			
Local solo exercises.	OR COMMANDING OFFICER'S REPORT:			
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	D-14	#155	
A/C bounced on landing then stalled, dropping a wing and grazing the wing				
tip on the runway.				
	RECOMMENDATIONS:			
PRIMARY CAUSE:	_			
40. Heavy landing - flying into grow	and.			
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER NIL.			
SECONDARY CAUSE OR CONTRIBUTING FACTORS:				
SECONDARY CAUSE OR CONTRIBUTING FACTORS:				
	RECORDED BY	7	D	DATE
	CHECKED BY			DATE