

CASPIR Aircraft Accident Cards

Serial: 8314

Title: Avro Anson Mk. II serial:8314 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-May-05. Anson II s/n 8314. This accident involved 2 people. Hamber EC, MacDonald JDC

Keywords: RCAFAnson II,8314,5 SFTS,5 Service Flying Training School,Aerodrome,1943-May-05,Hamber,MacDonaldRCAF L20

Created: 1943-05-05

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8314>

DUTY ON WHICH ENGAGED:

Weather Test

COURT OF INQUIRY, INVESTIGATING OFFICER

D.14#8

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Passenger inadvertently raised
u/c after landing.

DATE:

COMPOSITION:

LTC / P000000 / UCDR

RECOMMENDATIONS:

Passengers be warned by pilot to avoid touching
controls.

PRIMARY CAUSE:

~~57. Miscellaneous~~

7. OTHERS

7

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~14. Misuse of Controls~~

u/c DRILL -

ON GROUND

33

RECORDED BY

DATE

CHECKED BY

DATE