

CASPIR Aircraft Accident Cards

Serial: FP922

Title: Avro Anson Mk. II serial:FP922 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-May-19. Anson II s/n FP922. This accident involved 2 people. Cook GA, Fleming JB

Keywords: RCAFAnson II,FP922,15 SFTS,15 Service Flying Training School,Milo Alberta,1943-May-19,Cook,FlemingRCAF L20

Created: 1943-05-19

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP922>

DUTY ON WHICH ENGAGED:

Navigation low flying. Cross country.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Sgt. Cook attempted to show Lac. Fleming how difficult it was to judge height over water, and in showing him struck the water with propellor tips and shattered them.

PRIMARY CAUSE:

32. Pilot error.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14 #36

DATE:

COMPOSITION:

ILCC/PP/PS

RECOMMENDATIONS:

Sgt. Cook has been placed in close arrest and grounded. It is strongly recommended that he be discharged from the service.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

16. Unauthorized low flying or aerobatics

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____