



DUTY ON WHICH ENGAGED:

Dual instruction intended.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Student instructed to start A/C engines by instructor. Proceeded unauthorized taxiing, lost control striking Anson 8384 which was parked.

DATE:

COMPOSITION:

RECOMMENDATIONS:

MVLT  
TCN/PT  
MA/XE

D-14 #37

PRIMARY CAUSE:

~~9. Hitting other aircraft.~~

9. COLLISIONS.

9

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed. 7 days detention.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~17. Disobedience of standing orders.~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_