

CASPIR Aircraft Accident Cards

Serial: 3566

Title: Fleet Fort serial:3566 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-May-27. Fleet Fort II s/n 3566. This accident involved 2 people. Gifkins GE, Lourie JW

Keywords: RCAF Fleet Fort II,3566,3 WS,3 Wireless School,Stevenson Field
Winnipeg,1943-May-27,Gifkins,LourieRCAF L20

Created: 1943-05-27

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3566>

DUTY ON WHICH ENGAGED:

Wireless exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14 # 7.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pilot was taxiing up to line of A/C COMPOSITION:

on tarmac, and stopped before coming into the line, waiting for ground crew to park A/C ahead. Pilot did not observe red painted stand 2 ft. high, holding fire extinguishers, and let A/C ease forward slowly. Tip of prop. was damaged when hitting this wooden stand.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~2. Hitting obstructions.~~

9. COLLISIONS.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE