

DUTY ON WHICH ENGAGED:

First solo flight in circuit.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14 #72

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C started to swing after landing,
ground looped.

DATE:

8/10/55

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

25. Inexperience

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

38. Ground loop.
61. Swinging on landing.

RECORDED BY

DATE

CHECKED BY

DATE