

CASPIR Aircraft Accident Cards

Serial: AS685

Title: Airspeed Oxford Mk. I serial:AS685 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-May-07. Oxford II s/n AS685. This accident involved 2 people. Jackson DAF, Witchell SP

Keywords: RAFOxford II,AS685,35 SFTS,35 Service Flying Training School,Aerodrome,1943-May-07,Jackson,WitchellRCAF L20

Created: 1943-05-07

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS685>

DUTY ON WHICH ENGAGED:

Navigation training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

D-14. #6.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Port engine failed completely when pilot returning from cross country flight. Cockpit check failed to reveal reason and pilot proceeded to base on stbd. engine, gradually losing height. Owing to lack of height, final approach was made at 80 m.p.h. with almost full throttle on stbd. engine and no flaps. A/C stalled, port wing PRIMARY CAUSE: striking ground and A/C cart-wheeled.

DATE:

COMPOSITION:

22/10/41

RECOMMENDATIONS:

~~54. Engine failure in the air.~~

~~Cause obscure~~

17 FORCED LANDING 17

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~25. Inexperience.~~

26. ENGINE TROUBLE - 2
ACCIDENT.

RECORDED BY

DATE

CHECKED BY

DATE