

152	2	81	60	59	58	57	56	55	54	53	52	51	50	49	48	47	46	45	44	43	42	41	40	39	38	37	36	35	34	33	32	31	4	2	1	7	4	2	1	MONTH	FORCED LANDING	1	TAXYING	LANDING	TAKE-OFF	FLIGHT	STAIRY	FATAL	INJ.	3RD	5	2	M	N
UNIT	COM.	PLACE	DATE	TIME	H.Q. FILE	A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT	PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	NO.	DATE	NO.	CHECKED	ENGINE	ENGINE NUMBER (S)	INST.	NIGHT	ON TYPE	TOTAL	SOLO	DUAL	SOLO	DUAL	ACCIDENT CLASSIFICATION																					
																																		Weyburn	2	M.A.	16.6.43	0200	1300-AJ.944	Harvard II	AJ.944	C.1	X				X	Nairn, G.D.T.	FO	125980	FI	Nil	No.	17.6
M.A.	1300-AJ.944	X	X	Nil	17.6	80	65	77	527	76	550	142	603	ACCIDENT CLASSIFICATION																																								

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Dual night flying circuits & landings

NATURE OF ACCIDENT:

Pupil pilot made one wheel landing,
a/c swung off runway, groundlooped,
causing damage to oleo leg.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~38. Groundloop~~ 2

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

54 w/c Strain.

34

ACTION TAKEN:

Nil