

62	61	60	59	58	57	56	55	54	53	52	51	50	49	48	47	46	45	44	43	42	41	40	39	38	37	36	35	34	33	32	31	
ACCIDENT CLASSIFICATION																																
TYPE OF A/C	UNIT	41 S.F.T.S. Weyburn, Sask.	COM.	2	PLACE	M.A.			DATE	21-6-43	TIME	1005	COMMAND																			
	A/C TYPE	Harvard 11B Harvard 11B		NO.	FE326 D FE346	CRASH CAT.	C 2 D		S.E.	X	M.E.			DAY	X	NIGHT																
TYPE OF UNIT	PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		MONTH																						
	MacDonald R.A.		Lac.	1651557	PI	NIL. (FE326)		NO.	DATE		STAGE OF FLIGHT																					
CATEGORY	ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				NO. 17			CHECKED K																				
	Wasp AN1 1486/41-12931 Nil.		Wasp S3H1 9314/132 Nil.		INST.	NIGHT	ON TYPE		TOTAL		#99																					
				14	5	SOLO	DUAL	SOLO	DUAL																							
						11	19	49	65																							
ACCIDENT CLASSIFICATION																																
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	RAF	M	N

4
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKE OFF
FLIGHT
STATRY
FATAL
INJ
3RD
INJURY
S

PURPOSE OF FLIGHT:

Taxiing prior to take off.

TECHNICAL OFFICER'S REPORT:

Nil.

NATURE OF ACCIDENT:

Pupil taxiing off apron struck a parked A/C.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other aircraft.~~

9

9. collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

~~21. Carelessness.~~

ACTION TAKEN:

Pupil grounded 1 month and awarded 7 days C.C.
Log book endorsed.