

## CASPIR Aircraft Accident Cards

---

**Serial:** 2982

**Title:** North American Harvard Mk.II serial:2982 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-June-21. Harvard II s/n 2982. This accident involved 1 person. Day FA

**Keywords:** RAFHarvard II,2982,34 SFTS,34 Service Flying Training School,Aerodrome,1943-June-21,DayRCAF L20

**Created:** 1943-06-21

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2982>



PURPOSE OF FLIGHT:

) Armament exercises.

TECHNICAL OFFICER'S REPORT:

No technical defect.

NATURE OF ACCIDENT:

) Landed at base. After touch down  
) the A/C ran straight for 40 yds.,  
) then swung to left. As pupil was  
) checking with swing, his stbd. tyre  
) burst and the A/C ground looped.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

) ~~38. Ground loop.~~

2

) 2. *Swung.*

SECONDARY OR CONTRIBUTORY FACTORS:

) ~~45. Tire trouble.~~

) ~~35. Cross winds and gusts.~~

) ~~61. Swinging on landing.~~

37

ACTION TAKEN:

Pilot's Log Book endorsed.