

CASPIR Aircraft Accident Cards

Serial: FE301

Title: North American Harvard Mk. IIB serial:FE301 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1943-June-23. They are: Harvard IIB s/n FE349, Harvard IIB s/n FE301. This accident involved 2 people. Taylor AE, Spikins WC This accident had 1 fatality. Leading Aircraftman Alfred Edward Taylor RAFVR Killed in Flying Accident service no:1621800 Harvard FE349

Keywords: RAFHarvard IIB,FE301,41 SFTS,41 Service Flying Training School,Macoun Saskatchewan,1943-June-23,Spikins,TaylorRCAF L20

Created: 1943-06-23

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE301>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Formation flying.

NIL

NATURE OF ACCIDENT:

Pilot of FE301 was carrying out R/T practice when pilot of FE349 attempted to roll round him. There was a collision. Pilot of FE301 used parachute successfully, pilot of FE349 apparently did not attempt to leave aircraft.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~26. Collision in the air.~~

COLLISIONS. A/C.

SECONDARY OR CONTRIBUTORY FACTORS:

~~17. Disobedience of standing orders.~~ ACTION TAKEN:

DISOBEDIENCE OF ORDERS

41