

CASPIR Aircraft Accident Cards

Serial: 2627

Title: North American Harvard Mk.II serial:2627 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-June-23. Harvard II s/n 2627. This accident involved 1 person. Cresswell-turner A

Keywords: RAFHarvard II,2627,34 SFTS,34 Service Flying Training School,Aerodrome,1943-June-23,Cresswell-turnerRCAF L20

Created: 1943-06-23

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2627>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Armament exercises.

No technical defect.

NATURE OF ACCIDENT:

Pupil returned to base and carried out a cross wind landing. After touching down on the runway, the a/c started to swing and the stbd oleo leg collapsed, and a/c ground looped.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

38. Ground loop

SECONDARY OR CONTRIBUTORY FACTORS:

35. Cross winds and gusts.

ACTION TAKEN:

Nil